



## Schnittstellen SolidWorks & Mastercam X<sup>2</sup> & VDA (Stand 2007-04-02)

◦ SolidWorks® aktuellste Version Import + Export	(*sldprt, *.sldasm, *.slddrw)
◦ eDrawings® aktuellste Version Import + Export	(*eprt, *.easm, *.edrw)
◦ Mastercam® aktuellste Version Import + Export	(*mcx, *.mc9, *.mc8, *.mc7)
◦ Varimetrix® VX Version 12.7 Import + Export	(*vx, *.xvx, *.vxm, *.vxn)
◦ ProE® Import + Export	(*prt, *.prt.*, *.xpr, *.asm, *.asm.*, *.xas)
◦ Parasolid® Import + Export	(*x_t, *.x_b, *.xmt_txt, *.xmt_bin)
◦ STEP Import + Export	(*stp, *.step)
◦ SAT (ACIS) Import + Export	(*sat)
◦ Autodesk Inventor® nur Import	(*ipt, *.iam)
◦ Solid Edge® nur Import	(*par, *.psm, *.asm)
◦ Cadkey® nur Import	(*prt, *.ckd, *.cdl)
◦ Rhinoceros® 3D NURBS nur Import	(*3dm)
◦ VDA-FS Import + Export	(*vda)
◦ IGES Import + Export	(*igs, *.iges)
◦ AutoCAD® Import + Export	(*dwg, *.dxf)
◦ StereoLithographie-dateien Import + Export	(*stl)
◦ Catia® Graphics Import + Export	(*cgr)